

24 HOUR GENERATION CHECKLIST Approved For Release 2002/06/13 : CIA-RDP69B00041R001600010046-1 BY 1817 SEC 121 C SEC 121 F /mo/60

ITEM	TASKS REQUIRED	H-HOUR START	H-HOUR COMP	ACTUAL TIME COMP	TIME COMP		CP CALLED	
					PRI	SEC	PRI	SEC
1	MAINTENANCE ALERTED		H-24	1010				
2	DCM MEETING		H-23	0930				
3	MAINT SECURE NITROGEN, OXYGEN		H-23	1110				
4	PCL SECURE TRUCKS		H-23	1110				
5	START MISSION AIRCRAFT PREFLIGHT	H-22:30	H-00:30	1040				
6	RECEIVE FUEL LOAD FROM FLIGHT PLANNING		H-22:30	1140				
7	RECEIVED 25X1A		H-22	1210				
8	TEB AND REFUEL	H-22	H-19	1510	1345	1230	1400	1400
9	ARC-50 CODES RECEIVED		H-22	1210				
10	COMMO AND IFF PREFLIGHT	H-22	H-18	1610	1100	1000		
11	SELECT RECOVERY CREW AND GIVE TO DCM	H-20	H-16	1810				
12	INS PREFLIGHT	H-18	H-16	1810	1100	0900	1105	1030
13	25X1D	H-16	H-13	2110	1710	1330	1715	1400
14	PACKAGE DATA RECEIVED		H-13:45	2025				
15	PACKAGE LOADED (CALL SECURITY BEFORE MOVING PACKAGE)	H-13	H-08:30	0140	0030	0030	0115	0115
16	25X1D	H-13	H-08:30	0140	2315	2300		
17	POL SEND 25X1A		H-10:45	2325				
18	LOX TOP OFF	H-4	H-03:30	0640	2100	2200		
19	NITROGEN TOP OFF 25X1D	H-4	H-03:30	0640	0645	0650		
20	AIRCRAFT STATUS BRIEF: CC, INS, PKG & DCM	(0640)	H-03:30	H-3	0610			
21	START INS WARMUP		H-03:30	0640	0640	0640	0645	0650
22	INSTALL CSC MAGAZINE IN NOSE	H-03:30	H-3	0710	0710	0600		
23	INS DATA TAPE LOADING	H-02:30	H-2	0810				
24	PACKAGE I HELIUM PURGE Q-BAY	H-2	H-00:30	0940				
25	PERSONAL EQUIPMENT LOADED	H-02:15	H-2	0810				
26	MAINT CALL SECURITY TO STERLIZE COCKPIT	H-2	H-01:50	0820				
27	COCKPIT SET UP PER CODE SHEET		H-01:50	0820				
28	VIEWFINDER LOADED WITH FILM	Approved For Release 2002/06/13 : CIA-RDP69B00041R001600010046-1	H-01:30	H-1	0910			
29	ENGINEER CHECK AIRCRAFT							

24 HOUR GENERATION CHECKLIST (CONT'D) APPROVED FOR RELEASE 2002/06/13 : CIA-RDP69B00041R001600010046-13) SEC 127

ITEM	TASKS REQUIRED	H=HOUR START	H=HOUR COMP	ACTUAL TIME COMP	TIME COMP		C.P. CALLED	
					PRI	SEC	PRI	SEC
30	ENGINE START		H-00:30	0940				
31	TAXI		H-00:20	0950				
32	RECOVERY GEAR IN PLACE		H+1	1110				
				1411				
	POST MISSION LANDING CHECKLIST			1410				
1	LAND AND COOL AIRCRAFT	L+00:00	L+00:30	1440				
2	SECURE ACFT AND SERVICE ENG OIL	L+00:30	L+01:15	1525				
3		25X1D	L+00:30	L+01:15	1525			
4	REMOVE VIEWFINDER FILM STRIP AND MAPS	L+00:30	L+01:15	1525				
5		25X1D	L+00:30	L+01:15	1525			
6	MAINTENANCE DEBRIEF	L+00:45	L+01:15	1525	1455			
7		25X1D	L+01:00	L+01:15	1525			
8	MOVE ARTICLE INTO HANGAR	25X1D	L+01:15	L+01:30	1540			
9	(NOTIFY SECURITY TO CLOSE HANGAR DOORS)	L+02:30	L+02:30	1640	1445			
10	DCCM FOR	25X1A	L+02:30	1740				
11	CO		L+04:15	1825				
12	"TAKE" TO SUPPLY (NOTIFY SECURITY BEFORE MOVING TO SUPPLY)		L+05:00	1910				
13	PACKAGE SUBMIT	25X1A	L+05:00	1910	1550			
14	SECURITY	25X1D	L+05:00	1910				
15	RUN TO SECURITY		L+05:00	1910				
16	SECURITY		L+09:00	2310				
17	IN3 SUBMIT	25X1A	L+10:00	0010	1630			